

TECHNICAL SPECIFICATIONS

Equipment: Multi-function Printer (for DOBS)	Code:
Date Prepared: April 21, 2022	


Particulars	Specifications
PRINTING	
Speed	Up to 40ppm (Letter)
Time to first Page	As fast as 7.2 seconds
Print Resolution	Black: 2400 (2400 x 600 dpi), 600 x 600 dpi
Memory	Standard: 512 MB
Recommended Monthly Page Volume	Up to 4000 pages
Maximum Monthly Duty Cycle	Up to 80000 pages per month
Compatibility	Must work with LANDBANK's existing Digital On-Boarding System (DOBS)
COPYING	
Copy Speed	Up to: Black: 42ppm (Letter)
Time to first copy	Less than 10 seconds
SCANNING	
Scanner Type / ADF Scan Flatbed scanner	Flatbed scanner with ADF / DADF (single pass Duplex)
A4/Ltr Duplex Scan Speed	Up to: Black: 92 / 96 sides/images per minute Color: 40 / 42 sides/images per minute
A4/Ltr Simplex Scan Speed	Up to: Black: 46 / 48 sides/images per minute Color: 20 / 21 sides/images per minute
ADF Paper Input Capacity	Up to: 50 pages 20 lb or 75 gsm bond
FAXING	
Modem Speed	ITU T.30, V.34 Half-Duplex, 33.6 Kbps
SUPPLIES	
Cartridge	Estimated Yield up to: Standard 3,000 pages
Imaging Unit	Estimated Yield up to: Standard 30,000
PAPER HANDLING	
Included Paper Handling	100-Sheet Multipurpose Feeder, Integrated Duplex, 150-Sheet Output Bin, 250-Sheet Input
Optional Paper Handling	550-Sheet Tray
Paper Input Capacity	Up to 900 pages or better 20 lb or 75 gsm bond
Paper Output Capacity	Up to 150 pages 20 lb or 75 gsm bond
Media Types Supported	Paper Labels, Card Stock, Plain Paper, Envelopes Refer to the Paper & Specialty Media Guide
Media Sizes Supported	A6, Oficio, 7 3/4 Envelope, 9 Envelope, JIS-B5, A4, Legal, A5, Letter, Statement, Executive, Universal, DL Envelope, Folio, 10 Envelope
General Information	
Standard Ports	Gigabit Ethernet (10/100/1000), USB Compatible with USB 2.0 Specification (Type B)
Noise Level	Operating: 54 dBA (Print) / 59 dBA (Copy) / 58 dBA (Scan)
Specified Operating Environment	Recommended Temperature: 10 to 32 Degrees Celsius; Humidity: Up to 80% Relative Humidity
Weight	17.8 kg or lighter



Revised Annex D-7

Additional requirements:


Qualification Requirement	Documentary Requirement
<p>a. Principal/Dealer must have at least one (1) service center or service technician & authorized reseller of consumables in the following areas:</p> <ol style="list-style-type: none"> 1. Region I or CAR – (preferably La Union, Pangasinan) 2. Region II – (Preferably Santiago City) 3. NCR or Region III or IV –(preferably NCR) 4. Bicol or Samar – (preferably Legazpi) 5. Region VI or VII or Leyte- (preferably Cebu City) 6. Mindanao – (preferably Davao City) <p>In case only service engineers are available in the above listed areas, at least one (1) service center must be located in NCR, Visayas and Mindanao.</p>	<p>a.1 List of names of the service technicians with resume.</p> <p>a.2 List of service centers' locations, contact persons and telephone numbers.</p> <p>a.3 List of local parts center/depot/reseller for the mentioned areas with complete address and contact details where spare parts will be available.</p>
<p>b. Service for repair /replacement of parts.</p> <p>c. Four (4) years warranty</p> <p>d. Bidder must be an authorized dealer of the product/brand.</p> <p>e. Contact details of the supplier on the units.</p> <p>f. Compatibility</p> <p>g. All units must be brand new.</p>	<p>b.1 Repair/replacement of parts must be accomplished within 48 hours upon.</p> <p>b.2 The service for repair must be done onsite.</p> <p>c.1. All parts of the multi-function printer must be covered by the warranty except consumables and under the following conditions: damages caused by fire, earthquake, flood, spilling of food and drinks, roof leakage, civil disturbance, and accidental dropping of the unit. And shall commence upon delivery of the unit at LBP warehouse.</p> <p>d.1. Certification from the Manufacturer that the bidder is an authorized dealer of the product/brand.</p> <p>e.1. Each equipment must have a Sticker containing the contact number of the supplier for the repair or any issues concerning the unit.</p> <p>f. Should be compatible with existing Digital On-Boarding Systems (DOBS) of the Bank. "Plug and Play", after installation of the Driver.</p>

Prepared by:


EDWARD A. JUAN
 ITO, NOD



CATHARINE P. ZULUETA
 SSIO, SID 

Checked by:


ARCHIEVAL B. TOLENTINO
 IT Manager

Approved By:


ENRIQUE L. SAZON JR
 Vice President, NOD


AURELIA M. LAVILLA
 Assistant Vice President, SID